

John Jay Park MPPA, ADA Ramp and Entrance Plaza Pavement

(State of Good Repair)

Located near East 77Th Street and Cherokee Place, in the Borough of Manhattan.

Community Board 8
May 11, 2023
Max Goodstein RLA, NYC Parks

Total Budget: \$1m

City Council District 05, Julie Menin

Project Size: 0.90 ac

Goals

- Provide safe pavement surfaces for all users
- Create and maintain ADA accessibility
- Facilitate active recreation
- Restore site drainage patterns













Site 50 FT



State of Good Repair John Jay Park | Project Location



Source: http://www.nyc.gov/floodhazardmapper

Base Flood Elevation (BFE):

Flood Hazard Zones

2015 Preliminary Flood Insurance Rate Map

V Zone (100-year floodplain subject to wave action)

Areas along coasts subject to inundation by the 1% annual chance flood event with additional hazards associated with storm-induced waves.

A Zone (100-year floodplain)

Areas subject to inundation by the 1% annual chance flood event.

Shaded X Zone (500-year floodplain)

Areas within the 0.2% annual chance floodplain, areas of 1% annual chance flooding where average depths are less than 1 foot, areas of 1% annual chance flooding where the contributing drainage area is less than 1 square mile, and areas protected from the 1% annual chance flood by a levee.

Limit of Moderate Wave Action (LiMWA)

The inland limit of the area expected to receive 1.5ft or greater breaking waves during the 1% annual chance flood event. Data from 2015 PFIRMs.

Future Floodplain 2050s

Future 1% Annual Chance Floodplain (100-year)

Future 0.2% Annual Chance Floodplain (500-year)

Resources (Links):



NYC Parks: Design and Planning for Flood Resiliency



NYC MOCR: Climate Resiliency Design Guidelines (v4.0)



State of Good Repair
John Jay Park | Flood Risk (Coastal)





- 1 And 2 Family Residential
- Multi-Family Residential (Walkup)
- Multi-Family Residential (Elevator)
- Mixed Use
- Commercial & Office
- Industrial & Manufacturing
- Transportation / Utilities
- Public Facilities & Institutional
- Open Space And Outdoor Recreation
- Parking
- Vacant Land
- Other



Landmarks

Landmarked site


Site is not Landmarked



1 - Entrance Area pavement with asphalt structural damage




2 - Entrance Area pavement with asphalt structural damage





1 - Empty Tree pit and asphalt structural damage



2 - Western Staircase to remain, Minor repair as needed. Lights to remain.





1 - Eastern Staircase to be replaced with new steps and ADA ramp



2 - Eastern Staircase to be replaced with new steps and ADA ramp. Drinking fountain out of contract limit and to remain.





1 - MPPA with asphalt structural Damage. Drinking fountain in MPPA to be replaced with ADA approved Type "E" Hi-LO



2 - MPPA with tennis court and painted games.





1 - MPPA with basketball courts




2 - MPPA with has many different uses



Existing Conditions







Scope of Work

Entrance Plaza


- Full depth asphalt
- All benches to remain, no replacement needed

MPPA

- Full depth asphalt replacement
- New basketball backstops
- Color seal for basketball and tennis
- New type 'E' Hi-Lo Drinking fountain

ADA Ramp

New concrete ramp to make MPPA ADA accessible







Full Depth Asphalt



Color Seal Asphalt



Single Post Basketball Backstops



Type E drinking fountain



ADA Compliant Handrail

